Estimated Cost of Compliance Proposed Child Day Care Center Rules Alpena Youth Center

R 400.5205 Rule 205 (1)(f)

For Infant Room Split

COST

3.5 and 7 - Add another sink to each area

3,500.00

Involves: Busting out concrete

Replacing tile

Additional Plumbing Removal of existing door Laying up old door opening

For Toddler Room Split

COST

1 and 7 - Add another sink to each area

2,600.00

Involves: Busting out concrete Replacing tile Additional Plumbing

Total Construction Cost to Center for Infant Room Split \$15,650.00 Total Construction Cost to Center for Toddler Room Split \$18,100.00

The estimate time the rooms must be closed for construction is approximately 4 weeks. The total loss in tuition would be close to \$2,700.00 for the infant room or 3,100.00 for the Toddler Room. The Chance we take of people finding new permanent daycare during this time could reach in excess of 25,000.00 for the year.

Last year, due to the economy and unemployment rate in our community, the Alpena Youth Center had a loss of 11,000.00 for 2004 year end. This year does not look much better. Where will we find the money for these renovations?

Plans for Compliance with Proposed Licensing Rules

R 400.5101 Rule 101. (b) "Ages" defined And Rule 101 (j) "Group size"

See circled #'s on drawing

| See circled #'s on drawing | |
|--|-----------------|
| Splitting Infant Room | |
| | COST |
| 8 - Wall built down center of room | 2,450.00 |
| Involves: Removing and replacing floor tile and ceiling tile | · |
| 4 - New entrance to Infant portion of room | 2,200.00 |
| 1 - Remove walls to existing Infant Nap Room | 1,700.00 |
| Involves replacing ceiling tiles and floor tiles | |
| 2 and 6 - New carpets for each room | 2,200.00 |
| 9 - Build new Diapering Area | <u>3,600.00</u> |
| Involves: Busting out concrete floor | 12,150.00 |
| Plumbing Cabinat unit with sists | |
| Cabinet unit with sink | |
| re-tiling | |
| Splitting Toddler Room | COST |
| 9 - Half Wall built down center of room | 1,800.00 |
| Involves: Removing and replacing floor tile | 1,000.00 |
| 2 and 3 - Adding new entrance and exit doors | 4,000.00 |
| 5 and 4 - New carpets for both areas | 2,200.00 |
| 8 - Add food prep area | 3,600.00 |
| Involves: Busting out concrete floor | -, |
| Plumbing | |
| Cabinet unit with sink | |
| re-tiling | |
| 6 - Add Restroom | 3,900.00 |
| | 15,500.00 |

R 400.5103a Rule 103a

Lead Caregivers

9 CEU's/90 clock hours

90 hours overtime pay

Mileage

Cost of training

X 3 Lead Caregivers

4,050.00

315.00 plus 300.00 at least

\$4,665.00

2 of our Leads already have degrees.

These are just the rules that will cause a financial hardship for our center. I am very concerned about many more of them. I am concerned that some of the new rules will cause hardships for our children and their parents. A detail of these concerns will follow.

Prepared by: Charleen Dubie, Director Alpena Youth Center

R 400.5102a Rule 102a.

| Caregivers | | <u>COST</u> |
|---------------------------------------|--|---|
| 1 ⁸¹ year- 8 clock hours | 8 hours overtime pay Mileage Cost of trainning X 9 caregivers | 756.00 100.00 plus <u>90.00</u> at least \$946.00 |
| 2 nd year - 12 clock hours | 12 hours overtime pay Mileage Cost of training X 9 caregivers | 1,134.00 100.00 plus <u>90.00</u> at least \$1,324.00 |
| 3rd year - 16 clock hours | 16 hours overtime pay Mileage Cost of training X 9 caregivers | 1,512.00 100.00 plus <u>90.00</u> at least \$1,702.00 |

Lead Teachers

| 1 st year- 8 clock hours | 8 hours overtime pay Mileage Cost of trainning X 5 Lead caregivers | 600.00 60.00 plus <u>50.00</u> at least \$710.00 |
|---------------------------------------|---|--|
| 2 nd year - 12 clock hours | 12 hours overtime pay Mileage Cost of training X 5 Lead caregivers | 900.00 60.00 plus <u>50.00</u> at least \$1,010.00 |
| 3 rd year - 16 clock hours | 16 hours overtime pay Mileage Cost of training X 5 Lead caregivers | 1,200.00 60.00 plus <u>50.00</u> at least \$1,310.00 |